

# 1D Wireless Laser Barcode Scanner User Manual



Version



Power off (Note ,After scan this barcode there will be a long beep ,then scanner goes to power off status )

## Introduction

This is a simple user's guide, please contact local distributor for more support and details.



Factory Default



Forced pairing

### Pair Instruction:

Step 1: Scan "Factory Default"



Step 2: Connect Data receiver to host device.

Step 3: Scan "Forced pairing "during the data receiver led indicator flashing, there will be two beeps after succeed pair



### 3 Optional Wireless Mode



Inventory



Normal



Automatic storage (default)

Remark:

- 1) Normal Mode: the data will be uploaded to host device immediately after scan, out of range it will not save the data, and there will be 2 alarm beeps out of range;
- 2) Inventory Mode: the data will be saved in the memory chip, and upload data to host device as instructed;
- Eg: scan the "upload all data and clear", the scanner will upload all data saved in the memory chip and cleared the original data;
- 3) Automatic storage Mode: the data will be uploaded to host device immediately after scan if the scanner in range, the data will saved in the memory chip if the scanner out of range which will heard 2 alarm beeps , press the scanner trigger to upload the saved data after back to range, and the original data in the memory chip will be cleared.

### Data Upload Instruction in Inventory Mode



Upload all data and clear  
(Note: Upload all stored data and clear them)



Upload all data But not clear  
(Note: upload all stored data and do not clear the data)



Upload one data and delete



Upload one data But not delete



Display all data



Data delete

### Scan Mode



Manual (Default)



Continuous



Auto-Flashing

### Auto-sense Mode



Enable



Disable

### Image Inverted



Direct



Reverse

### Buzzer



ON



OFF



High



Low



No upload successful notifications  
(Note: when the scanning gun scans this bar code successfully, the upload data would make a sound "Beep".)



Upload successful notifications  
(Note: when the scanning gun scans this bar code successfully, the upload data would make a sound "Beep" twice.)

### Keyboard Language



USA (default)



Germany



France



British



Russia



Italy



Japan



Canada

### Keyboard Caps Lock Control



Capitalize



Lower case



Case Swap



None

### End Character



CR



CR & LF



None

### Symbology Configuration



Enable UPCA to EAN13



Disable UPCA to EAN13 (default)



Enable UPCE to UPCA



Disable UPCE to UPCA (default)



Enable EAN13 to ISBN



Disable EAN 13 to ISBN (default)



Enable EAN13 to ISSN



Disable EAN13 to ISSN (default)



Enable the 5-bit additional code



Enable the 2-bit additional code



Disable the additional code (default)



Hide front 1 digit character



Hide front 2 digit character



Hide front 3 digit character



Hide last 1 digit character



Hide last 2 digit character



Hide last 3 digit character



Prefix F7 before all barcodes